0.00

Memo

QC

Quality Control

NCR: Y	es /	No ·····				WORK ORDER NON-C	ONF	FORN	MANCE / UPDATE		DQA:	Date:	14-2-2; 14-7-14
DISPOSITION									AGAIN	ST DE	PARTMENT	PROCESS	/
Work Order: 108747 Part No. D 3196-4 NCR No. 14-3529						Rework Scrap Use-as-is X Work Order Update		Skid-tube Crosstube Machining Small Fab Thermoforming Finishing Large Fab Composite			b Prod. Eng. Coor. Quality Grant Coor. Quality Grant Coor. Other		
Root					-	otion of work order update		itial	Action		Sign &		
Cause		ite	Step	Qty	C	or Non-conformance	Chie	f Eng	Description		Date	Verification	QC Inspector
Equip/Tooling	× 13	() () () () () () () ()				9	Acceptable 1/14 Cosmotic only			DAS 12 9-89	5th 13 11 14	14/02/12	
Опаррточец				l		F/	AULT	CATE	GORY		<u>. </u>		
Landir	ng Gear					General							
	Bending Centre Not Concentric to O/S Cracks Crushed/Crimped Cuffs Heat Treat				o/s	Bend BOM/Route Broken/Damaged Burrs Contamination Countersink	H	nstruct Mainte Mislabe	on Incomplete ions Incomplete/Unclear enance eled		Ovalized Over/Under tolerance Part Incorrect Part Lost/Missing Part Moved Positioned Wrong		Pressure/Forced Temperature/Cure Weld Wrong Stock Pulled
	_ `		Strip in	Tube	<u> </u>	Cut Too Short	\vdash	Aisread	i	<u></u>	Power Loss/	Surge	Other
		oles in E		• •	_	Drill Holes	\mathbf{H}^{T}	Offset					
		•	eves in E		n	Drawing Sinish	\mathbf{H}		Calibration Sequence				
	_	-	quence st in Tub		<u> </u>	Finish Folio	\vdash		Dimensions				

Page 2

October-29-13 9:55:57 AM

Item ID:

D3196-4

10/29/13

Accept

N900040100

Setup Start

Revision ID:

Start Date:

Item Name:

Required Date: 10/29/13

Bar

Start Qty: 4.00 **Req'd Qty:** 4.00

Operation

Description

Date:

Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan:

Date:

Tooling:

SPC (Y/N):

Date:

Run

Stop

Sequence ID/ **Work Center ID**

130

130

Quality Control

QC

QC8- Inspect parts - second check

Memo

Run Hours

Set Up/

0.00

0.00

Tool ID Tool # Plan

Date:

Accept Code Qty

Reject **Qty**

Reject Insp. Number Stamp

140

140

HandFinish Hand Finishing Chemical Conversion Coat per QSI005 4.1

Memo

0.00

0.00

4 200 13-11-14

150

150 Powdercoat

Powder Coating

0.00

0.00

H & B-115.

											DQA:	Date	::
NCR: Yes / No						WORK ORDER NON-CONFORMANCE / UPDATE					OA Classed	Dete	
											QA Closed:	Date	:.
Work Orde	5 F					DISPOSITION				AGAINST DE	PARTMENT	PROCESS	
Part No NCR No.						Rework Skid-tube Crosstube Machining Small Fab Use-as-is Thermoforming Finishing Work Order Update Large Fab Composite		Water Jet Prod. Eng. Coor. Rec/Store/Packaging Supplier		Engineering Quality Other			
	_				•	'	,						
Root	ł				Descri	ption of work order update	ı	nitial	Act	ion	Sign &		
Cause		Date	Step	Qty	•	or Non-conformance	Ch	ief Eng	Descr	iption	Date	Verification	QC Inspector
Doc/Data Equip/Tooling Operator Material Setup Other Process Supplier Training Unapproved		<u> </u>											
						· · · · · · · · · · · · · · · · · · ·	AUL	T CATE	GORY				·
Landing Gear Bending						General Bend	Grain				Ovalized	. [Pressure/Forced
		Bending Centre Not Concentric to O/S Cracks				BOM/Route		Hardwa	re		Over/Under	tolerance	Temperature/Cure
						Broken/Damaged		Inspecti	on Incomplete		Part Incorre	ct [Weld
	Ш	Crushed/	Crimped			Burrs	L	Instruct	ions Incomplete/L	Jnclear	Part Lost/M	ssing	Wrong Stock Pulled
	Ш	Cuffs				Contamination		Mainte	nance		Part Moved		
		Heat Trea	it			Countersink		Mislabe	led		Positioned V	Vrong	_
		Inspection	n Strip in	Tube		Cut Too Short		Misread	I		Power Loss/	Surge	Other
		Ripples in	Bend			Drill Holes		Offset				_	

Out of Calibration

Out of Sequence

Outside Dimensions

Turning Sequence

Wave/Twist in Tube

Torque Waves in Extrusion

Drawing

Finish

Folio

108747

Page 3

October-29-13 9:55:57 AM Item ID: D3196-4 **Revision ID: Item Name:** Bar **Start Date:** Required Date: 10/29/13 Reference: Approvals:

Accept

N900040100

Setup Start

Stop

10/29/13

Start Qty: 4.00 Req'd Qty: 4.00

Cust Item ID:

Customer:

Process Plan:

Date:

Date:

Tooling: SPC (Y/N): Date:

Date:

Start Run

Stop

Sequence ID/ **Work Center ID** 160

Operation **Description** Set Up/ **Run Hours**

Tool ID Tool #

Accept Qty Code

Plan

Reject **Qty**

Reject Insp. Number Stamp

160

QC Quality Control QC3- Inspect Part Finish

Memo

0.00 DAS 27 0.00 13949 D

170

Identify as per dwg & Stock Location: 57259

170

Packaging

Packaging

Memo

0.00

180

QC21- Final Inspection - Work Order Release

0.00

120 QC

Memo

0.00

Quality Control

110111	NCR:	Yes /	No
--------	------	-------	----

											DQA.	Date.	
NCR:	CR: Yes / No					WORK ORDER NON-CONFORMANCE / UPDATE							
											QA Closed:	Date:	
Vork Ord	er:					DISPOSITION				AGAINST DE	PARTMENT	PROCESS	
Part No						Rework Skid-tube Crosstube Machining Small Fab Thermoforming Finishing Composite		Water Jet Prod. Eng. Coor. Rec/Store/Packaging Supplier		Engineering Quality Other			
Root					Descr	ption of work order update	I	nitial	Acti	on	Sign &		
Cause	·	Date	Step	Qty		or Non-conformance	Ch	ief Eng	Descri	ption	Date	Verification	QC Inspector
oc/Data uip/Tooling perator aterial tup ther ocess pplier aining approved													
						FA	AUL	T CATE	GORY				
Land	ing (3			_	General		ı		_	7	-	
		Bending Centre Not Concentric to O/S Cracks Crushed/Crimped				Bend BOM/Route Broken/Damaged Burrs			re on Incomplete ions Incomplete/Unclear		Ovalized Over/Under tolerance Part Incorrect		Pressure/Forced Temperature/Cure Weld Wrong Stock Pulled
		Cuffs				Contamination		Mainte	nance		Part Lost/Missing Part Moved		Wrong Stock Fulled
		Heat Trea	n Strip in	Tube		Countersink Cut Too Short	\vdash	Mislabe Misread			Positioned Wrong Power Loss/Surge		Other
	_	Ripples in				Drill Holes		Offset	;				
	<u> </u>	Torque W			¹	Drawing		ł	alibration				
		Turning Se	equence			Finish		Out of S	Out of Sequence				

Outside Dimensions

Wave/Twist in Tube

Folio


H:/FORMS/Quality Assurance\approved QA/NCRWO Rev G


DART AEROSPACE LTD	Work Order:	108747
Description: Bar	Part Number:	D3196-4
Inspection Dwg: D3196 Rev: C		Page 1 of 1


FIRST ARTICLE INSPECTION CHECKLIST


Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
34.625	+/-0.010	34.625			M-topp	111-08
33.650	+/-0.010	33.650			, ,	J
16.639	+/-0.010	16.639			y (
0.488	+/-0.010	.488			Vein	46-06
0.962	+/-0.005	.91.3	- 1		A	
0.464	+/-0.010	.464			7/	
0.504	+/-0.010	.504			اد	
Ø0.344	+0.006/-0.001	8.345	1		Å	
Ø0.660 x 100°	+0.008/-0.001 x 0.5°	1660X100°			11	
0.512	+/-0.005	, 571			"	
0.060 x 45°	+/-0.010 x 0.5°	.076X45°			J(
4.750	+/-0.010	4.750			M-tape	71-08
12.531	+/-0.010	12.531			/	
16.627	+/-0.010	16.627			5 1	
21.844	+/-0.010	21.844			18	
29.625	+/-0.010	29.625			1.	
0.250	+/-0.010	.250			Vern	MILLE
1.000	+/-0.010	1.600			/(
R0.125	+/-0.010	R.125			R-6-	
0.987	+/-0.010	.991			Ven	71.06

Meas	ured by:	Audited by:	Preliminary Approval:	
	Date:	13/11/11 Date: /3-11/4/	Date:	
Rev	Date	Change	Revised by	Approved
Α	04.04.20	New Issue	KJ/RF	
В	06.10.24	Dwg Rev updated	KJ/JLM ,	7/
С	11.06.21	Dwg Rev updated	KJ SKY	. [///












108747

DRAWING	3 NO.	TITLE		REV. C	DART AE	ROSPACE L	TD D.E.O. NO	O.	SHE	T NO.	SCALE
D3196		BAR		1	ENGINE	ERING ORDE	ER D3196-0	C-1	SHEET	2 OF 2	NTS
DRAWN	A	2رک	CHECKED		MFG. APPR.	91	APPROVED	10	DE APPR.	#	
DATE	08.08	.27	DATE	08.08.28	DATE	08.08.29	DATE	08.08.29	DATE	08.09.0	,4





SECTION F-F



NOTE: THIS CHANGE HAS BEEN DONE TO CLARIFY SLOT DIMENSIONS ONLY. NO CHANGES HAVE BEEN MADE TO THE PARTS SEE NCR 08-051 FOR FURTHER INFORMATION ALL OTHER INFORMATION REMAINS UNCHANGED

COPYRIGHT © 2003 BY DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DATA ZEROSPACE LTD.